

# STUDY ON THE SURFACE INFILTRATION RATE OF PERMEABLE PAVEMENTS

Eban Z. Bean, North Carolina State University, Raleigh, NC

This information was previously presented at ASCE/EWRI Conference in Salt Lake City, UT, in June 2004.

## Abstract

Asphalt surfaces have greatly increased the amount of pollutant-carrying runoff entering surface waters. To counteract this, permeable pavement can be installed to allow water to infiltrate, thus reducing runoff and acting as a filter. This study tested the surface infiltration rate of 27 permeable pavement sites in North Carolina, Maryland and Delaware. One of these sites in North Carolina was monitored to compare pollutant loads of asphalt runoff to those in infiltrate. Concrete grid pavers (CGP) and permeable interlocking concrete pavers (PICP) were tested with pavement ages ranging from six months to 20 years. Two infiltration tests were run on 14 CGP lots filled with sand. The initial test was on the existing condition of the surface and second test was run after the removal of the top layer of residue (1.3 - 1.9 cm) to simulate maintenance. Maintenance improved the infiltration rate on 13 of 14 sites. Analysis of the data showed that maintenance improves surface permeability at a confidence level of 99.8%. The median average infiltration rate increased from 5.0 cm/hr., for existing conditions, to 8.0 cm/hr after maintenance. Eleven PICP sites were also tested. Sites built in close proximity to loose fine particles had infiltration rates significantly less than sites free of loose fines. Averages of each condition are 60 cm/hr and 2000 cm/hr respectively. Even the minimum existing infiltration rates were comparable to those of a grassed sandy loam soil. Water quality data included in this study shows the results of six storms from June to October, 2003. With only a few storms to compare, only Zinc has been identified as having a statistically significant difference between infiltrate and runoff.

## Introduction

Permeable pavement is an alternative to traditional asphalt and concrete surfaces. Permeable pavement allows stormwater to infiltrate into either a storage basin below or exfiltrate to the soil and ultimately recharge the water table, while also potentially removing pollutants (EPA, 1999). Urbanization has a detrimental effect on our surface waters systems. Increased runoff rates from paved surfaces have increased peak flow through stream channels causing erosion and stream bank instability along with overland erosion (Leopold et al., 1964). Runoff from parking lots also carries pollutants, such as sediments, nutrients, and heavy metals, into surface waters. In an effort to reduce these effects of urbanization, many municipalities in North Carolina established regulations that limit the amount of impervious surface a property can have (Bennett, 2003). Permeable pavement is a potential solution; in lieu of 100% impermeable lots, perhaps a fraction of runoff can be reduced and pollutants be removed. As a result, the use of permeable pavement is poised to grow.

North Carolina has implemented a stormwater credit system for developed sites to manage onsite runoff. Several best management practices (BMPs) were given credits for pollutant reduction, sediment reduction, and peak flow detention. Permeable pavement has not been included in BMPs receiving credit because they may clog. However, North Carolina has not altogether prevented the use of permeable pavement. Permeable pavement is allowed to be used as a BMP under the "innovative BMP" classification. Innovative BMPs however must be monitored on an individual basis to assess their performance (Bennett, 2003). Few landowners have been willing to assume the cost of this required monitoring, thus limiting the number of permeable pavement installations.

Recent studies have found positive results using permeable pavement with respect to both runoff reduction and water quality improvement. The use of permeable pavement, instead of traditional asphalt has been shown to decrease surface runoff and lower peak discharge significantly (Pratt 1995; Booth,

1996; Hunt et al., 2001). Permeable pavement has also been shown to act as a filter of such pollutants as lead and automotive oil (Brattebo and Booth, 2003; Pratt, 1995).

Figures 1 and 2, below, show examples of permeable interlocking concrete pavers (PICP) and concrete grid pavers (CGP). PICP are concrete block pavers that create voids on the corners of the pavers. Photo-analysis was used to determine that open, or void, space is at least nine percent (9%) of the surface area. Most research that has been conducted has examined these block pavers as test surfaces (Balades et al., 1995; Pratt 1995; Gerritts and James, 2002). CGP paving systems are comprised of concrete blocks with voids inside and between the blocks. Photo-analysis was used to determine that open, or void, space is approximately (30%) of the surface. In this study, the sites examined had voids either filled with sand or No. 78 stone (ASTM D 448).



Figure 1: PICP



Figure 2: CGP

Pratt (1995) has found that clogging can be a result of fine particles accumulating in void spaces of permeable pavements. Smaller particles trap larger particles, therefore the rate of clogging increases as more fines are trapped (Balades et al., 1995). However, clogging can be limited by regular maintenance, either by vacuum sweeper or high pressure washing (Balades et al., 1995). Removing the top 15 - 20 mm (0.6 - 0.8 in.) of void space material for low to medium traffic areas substantially regenerates infiltration capacity. Permeable pavements in higher traffic areas improve somewhat when 20 - 25 mm (0.8 - 1 in.) of material is removed (Gerritts and James, 2002). Gerritts and James compared infiltration rates before and after removal of void space material, using a removal depth of between 1.3 - 1.9 cm (0.5 - 0.8 in.).

The goals of this study were as follows: (1) determine surface infiltration rates of each pavement system; (2) compare and evaluate these rates for the pavement systems; (3) analyze the impact maintenance has on revitalizing surface infiltration rates; (4) monitor pollutant levels of infiltrate compared to asphalt runoff; (5) offer basic siting guidelines based upon these results.

## Procedure

### Infiltration Measurements

Sixteen CGP and 11 PICP sites were tested in this study to determine infiltration rates. Double- or single-ring infiltrometers were used at each site to measure surface infiltration rates. Two sets of tests were run at 14 of the 16 CGP sites, one set to measure existing conditions, and one set to measure “maintained” conditions.

Each set of tests included three infiltration tests to help counteract variability in the surface conditions and infiltration rates. Locations for these tests were representative of the entire surface.

This study used ASTM D 3385, is the Standard Test Method for Infiltration Rate in Field Soils Using Double-Ring Infiltrimeter, as a basis to measure infiltration rates. This test measures infiltration rates for soils with a hydraulic conductivity between  $10^{-6}$  cm/s to  $10^{-2}$  cm/s. The test used during this study modified some of the methods and materials in ASTM D 3385 to operate more efficiently in this study’s environments and resources. The double ring infiltrometers used in this study consisted of two 16 gauge galvanized steel rings. The inner rings had a diameter between 28 cm and 30.5 cm. The outer

rings had diameters between 76 cm and 91 cm, or approximately three times the diameter of the inner rings.

Once locations were somewhat randomly selected for testing at each site, the infiltrometer rings were sealed to the surface using plumber's putty. The inner ring was then filled with water to a depth of approximately 50 mm above the testing surface to determine if there was any leakage to the outer ring. Once all leaks – if any - were plugged, both the inner and outer rings were filled to a depth between 125 mm and 175 mm. The initial level of water in the inner ring, outer ring, and current time (effectively time 0) were then recorded. Water was then allowed to infiltrate freely. During infiltration, inner and outer ring water levels were measured from a fixed point on the top of the ring down to the water level and then recorded with the time approximately every five minutes. Water was only added to the outer ring when it had dropped more than 10 mm below the inner ring water level to equalize hydraulic heads. A test was considered complete when either the inner ring ran dry or enough time had elapsed to determine the infiltration rate. The time needed to determine the infiltration rate was a minimum of 45 minutes.

As stated before, the third goal of this study was to compare existing condition infiltration rates to maintained condition infiltration rates for CGP pavements. At each site three existing tests were conducted and then three maintenance tests were conducted in different locations. An existing test was an infiltration test where the surface remained unaltered prior to the infiltration test. A "maintenance" test was an infiltration test where the void material was removed to a depth between 1.3 cm and 1.9 cm to simulate maintenance by a vacuum truck or street sweeper. For CGP sites, if the measured existing infiltration rates of a site were lower than 25 cm/hr, a set of maintenance tests was run.

Many PICP sites had infiltration rates too high to maintain a hydraulic head using the double-ring infiltrometer test. A modified test, known as a "surface inundation test" (Figure 4) was run at these sites. For the surface inundation test an inner ring of the double ring infiltrometer was sealed to the test surface and a scale was taped inside the ring. Using a five gallon bucket, water was quickly poured into the inner ring. Time was recorded from when the water started pouring in. The time was then recorded when the bucket emptied (along with the peak level of water inside the ring), and then every 30-60 seconds until the ring emptied. If the ring emptied in less than 30 seconds, then the time that the ring emptied was recorded. This test is neither as accurate nor as precise as the double-ring-infiltrometer test. However, this was a means of obtaining a rough of the surface infiltration rate.



Figure 3. Double-ring-infiltrometer tests.



Figure 4. Surface inundation test.

After the data was collected, the water levels were plotted functions of time for each test. The slope of the least squares line for each test was determined to be the surface infiltration rate of the permeable surface. If it was determined that removing the initial two or three data points from a test was more representative of the surface infiltration rate (improved  $R^2$  value), then those initial data points were omitted from the calculation of the least squares line. The infiltration rate stated for each site was determined for each set of infiltration tests by averaging the three results.

## Water Quality

The Mickey's Pastry Shop site is a parking lot that uses asphalt for the drive paths and PICP as parking stalls. Installed in 2001, water quality monitoring has taken place since June of 2003. Nutrient, metal, and sediment loadings of asphalt runoff were compared to those which infiltrate the PICP areas. To date, six storms have been analyzed.

During construction, a drainage pipe was installed to collect water samples beneath the pavement layers. The outlet of the 3" PVC drain pipe was controlled by a manual valve. Before and after each monitored storm, the pipe valve was opened to drain the storage basin. Collection was done the day following a rain event. Collection was taken by opening the valve and letting some water flush out the pipe for approximately 10-15s.

Runoff was collected using a Isco 67 sampler. A trough was installed at the edge of an asphalt drive. The sampler pulled samples from this trough ever 20 minutes into a single collection jar. These samples were also collected the day after a rainfall event. The jar was emptied after each sample to ensure that only one rain storm is being analyzed.

Both samples were analyzed by Tri-Test of Raleigh, NC. Samples were analyzed for concentrations of: total phosphorus (TP), total suspended solids (TSS), total Kjeldahl nitrogen (TKN), nitrate-nitrite (NO<sub>x</sub>-N), total nitrogen (TN), copper (Cu), and Zinc (Zn).

## Results

### Concrete Grid Pavers

Infiltration rates were measured from 16 sites with CGP. Figure 5 is a graphic showing the infiltration rates of the lots tested throughout NC. Of these, 14 sites were "maintained", and had their maintenance infiltration rate measured. (The "existing" or "unmaintained" and "maintained" were defined earlier in the Procedure section.) Of the two sites that did not have maintenance performed, the measured infiltration rate at one site was greater than 25 cm/hr, Kinston TS, and the other had an existing infiltration of 10 cm/hr, Wynn Plaza. The site with the lowest surface infiltration rate, Town of Cary Public Works (1.0 cm/hr), could be the result of a combination of factors (i.e. no maintenance and frequent heavy traffic). This site also was constructed in a clay soil area; however, since the surrounding area is relatively undisturbed, this may not be a significant factor.

Of the sites that had maintenance testing, 13 had noticeably higher infiltration rates than the "unmaintained" pavers. The only site that did not increase its infiltration rate was Blackman Beach Access. This anomaly was potentially due to a high infiltration rate of 22.2 cm/hr for one of the existing tests, while all other tests, existing and maintained, had infiltration rates less than 10 cm/hr. The mean and median average existing surface infiltration rates, where both rates were recorded, were 7.1 cm/hr and 5.0 cm/hr respectively; the mean and median average maintained surface infiltration rate was 11.8 cm/hr and 8.0 cm/hr, respectively. Comparing means, maintaining the lots increased the permeability by

66%.




Figure 5. Infiltration rates measured from CGP sites.

### Permeable Interlocking Concrete Pavers

Eleven PICP sites were tested; seven in Maryland, three in North Carolina and one in Delaware. Six of these sites were tested using only the surface inundation test, due to their high infiltration rates (>150 cm/hr) Havre de Grace maintained a hydraulic head just enough to fill the double-ring-infiltrometers for testing, but had an average infiltration rate average of 100 cm/hr. One of the three tests ran at the Penny Rd. site was a surface inundation test, however the other two were a double-ring-infiltrometer tests. The three remaining PICP sites had surface infiltration rates low enough to maintain a hydraulic head so that standard double-ring infiltrometer tests were able to be performed. The four sites which used double-ring-infiltrometer tests were located in close proximity to areas containing exposed fine soil particles, e.g. gravel drive, a river bed, a beach and a construction site. Figure 6 shows measured infiltration rates for permeable pavement applications using PICP or similar products. The last four infiltration rates are the four PICP sites affected by fine soil particles. It has been shown statistically that surface infiltration rates of sites located near fines are substantially lower than those rates from areas free from fines.




Figure 6. Infiltration rates for PICP applications.

### Water Quality

For water quality data from Mickey's Pastry Shop, differences in concentrations were determined to be significant if SAS returned p-values for the t-test of less than 0.05. Zinc was the only pollutant to have significantly different concentrations with a p-value of 0.002. Figure 7, below, shows concentration levels for Zinc.

Copper data ( $p = 0.18$ ) shows that for storms 1, 2, and 6, concentrations in runoff and infiltrate were relatively equal. However for storms 3, 4, and 5, infiltrate has lower concentrations of copper than the runoff. It should be noted that for storms two through six, the infiltrate concentrations of copper were less than the minimal detectable value (0.01 mg/L). There were not essentially no trends for TSS, TN and TKN, while there may have been an increasing trend for  $\text{NO}_x\text{-N}$  when comparing runoff from asphalt to the infiltrate. With more storms and data to compare, it will become more certain how well these pollutants, along with Zinc, are removed.




Figure 7. Zinc concentrations in runoff and infiltrate from six storms.

The other six pollutants monitored were: Cu, NO<sub>x</sub>-N, TKN, TN, TP and TSS. None of them were significant ( $p \leq 0.05$ ), however some showed a removal trend. Phosphorus ( $p = 0.13$ ) showed a strong tendency to have lower concentrations in infiltrate compared to runoff. Figure 8 shows concentration levels of TP. For four of the six storms, infiltrate concentrations of TP were less than half of that of the runoff concentrations, and for four of the storms, the infiltrate TP concentration was less than the minimum detectable value (0.05 mg/L).




Figure 8. Phosphorus concentrations in runoff and infiltrate from six storms.

### Analysis & Key Conclusions

There are several observations that can be drawn from this study. The first is that parking lot maintenance is a key to maintaining infiltration rates on pavements comprised of CGP, filled with sand. Thirteen of 14 sites had increased infiltration rates after removal of the top layer (1.3 cm typical depth) of accumulated void space material. Without maintenance the median average infiltration rate was 5.0 cm/hr, while with maintenance the median infiltration rate was 8.0 cm/hr. A SAS<sup>TM</sup> (2003) analysis showed that there was a statistically significant difference between existing and maintained infiltration rates to a 99.8% confidence. It can be stated with high confidence that maintenance significantly improved infiltration rates for the CGP sites with sand in this study.

Infiltration rates of PICP filled with gravel are not limited by their surface infiltration capacity provided they are sited in areas free of soil disturbances. The average PICP infiltration rate was 2000 cm/hr, while the PICP sites near disturbed soils with fines was 61 cm/hr, a decrease of almost 97%. A SAS<sup>TM</sup> (2003) test was run to determine if there was a significant difference between the infiltration rates of PICP near fines and free of fines. The analysis showed a significant difference in surface infiltration rates at a confidence level of 99.5%. PICP sites free of fines have significantly higher infiltration rates than PICP sites with sandy fines present in this study.

Lastly, each site tested, with the exception of three (Somerset Drive, Hargrove, and Town of Cary Public Works) had infiltration rates greater than 2.5 cm/hr. These rates are equal to or greater than infiltration rates expected for grassed sandy loam. Surface clogging in predominantly coarse grain soil

environments, therefore, does not cause permeable pavements to have surface infiltration rates reduced below some naturally grassed areas.

As a result of this study, suggested siting and maintenance guidelines are as follows:

1) For CGP sites filled with sand:

Maintenance, using a vacuum sweeper, should be performed on at least a yearly basis. Removing the top 1.3 cm of material accumulated within void spaces has been significantly shown to improve infiltration rates. Sand should then be backfilled into the void spaces to prevent sealing at a lower depth.

2) For PICP sites:

PICP lots installed for infiltration purposes should not be sited adjacent to areas with free fine particles. Fine particles have been shown to severely decrease infiltration rates.

After six storms, water quality analysis from Mickey's Pastry Shop in Goldsboro, NC, shows that the site had significantly lower concentrations of Zinc in infiltrate as compared to the asphalt runoff. With more storms, this may also be shown with pollutants such as Cu, TSS, TP and TKN. With only six events measured, these pollutants show trends of lower concentrations for infiltrate than runoff.

To conclude, there are several states, including North Carolina, which do not credit permeable pavement with reducing runoff. In regions with coarse grain soil (sandy soils) data from this study suggest that permeable pavement could be counted as truly permeable. Of 27 pavements tested only three sites had infiltration rates less than 1 in/hr, including the one site tested in a fine grain soil (clay soil) environment. Evidence suggests that, providing the following conditions are met, permeable pavements do reduce runoff to a significant extent: (1) the application is sited in a sandy or loamy sand soil, (2) is located in soils without seasonally high water tables, (3) the pavement is well-maintained, (4) proper construction materials and techniques are followed, (5) the pavement is essentially flat and away from disturbed clay soils, and (6) does not have overburdening structural loads.

### Acknowledgements

Several agencies and people have aided this research in many different ways. Thanks go to the Interlocking Concrete Pavement Institute, the North Carolina Department of Environmental Health and Natural Resources, which administers the EPA 319(h) grants, helped fund this study. The contributions of Brandon Eckrote, Lucas Sharkey, and L. T. Woodlief were critical to gathering infiltration data. Thanks goes to Jonathan Smith for his assistance and guidance throughout this study. The authors would like to thank Amy Moran and Mike Regans for their help in setting up data collection and analysis. Thanks goes to all of the property owners, town officials, and extension agents who assisted in site selection and background information for each site. Their assistance was vital to this study.

### References

- ASTM D 3385-03. Standard Test Method for Infiltration Rate of Soils in Field Using Double-Ring Infiltrometer. American Society for Testing and Materials. 10 Jun 2003. Conshohocken, PA
- ASTM D 448-03. Standard Classification for Sizes of Aggregate for Road and Bridge Construction. American Society for Testing and Materials. 10 Feb 2003. Conshohocken, PA
- Balades, J. D., Legret, M., and Madiec, H. (1995) Permeable Pavements: Pollution Management Tools. *Water Science and Technology*. 32(1): 49-56.
- Bennett, B. (2003) Personal communication. 3 November.
- Booth, D. B., Leavitt, J., and Peterson, K. (1996) The University of Washington Permeable Pavement Demonstration Project.
- Brattebo, B. O., and Booth, D. B. (2003) Long-Term Stormwater Quantity and Quality Performance of Permeable Pavement Systems. 1 July 2003 University of Washington, Department of Civil and Environmental Engineering, Seattle, W.A.

- EPA. (1999) Storm Water Technology Fact Sheet: Porous Pavement. EPA: 832-F-99-023. Washington, D. C.: Environmental Protection Agency.
- Gerritts, C., and James, W. (2002) Restoration of Infiltration Capacity of Permeable Pavers. In: Proceedings of 9th International Conference on Urban Drainage. ASCE. Portland, O.R.
- Hunt, W. F., Stephens, S., and Mayes, D. (2002) Permeable Pavement Effectiveness in Eastern North Carolina. In: Proceedings of 9th International Conference on Urban Drainage. ASCE. Portland, O.R.
- Leopold, L. B., Wolman, M. G., and Miller, J. P. (1964) *Fluvial Processes in Geomorphology*. San Francisco, C. A.: W.H. Freeman and Company.
- Pratt, C. J., Mantle, J. D. G., and Schofield, P. A. (1995) UK Research into the Performance of Permeable Pavement, Reservoir Structures in Controlling Stormwater Discharge Quantity and Quality. *Water Science and Technology*. 32(1): 63-69.
- SAS. (2003) *SAS User's Guide: Statistics*. Ver. 8.2. Cary, N.C.: SAS Institute, Inc.